






A	B	C		D
1	N100-120	420	397	1/3
2	N100-121	420	397	1/3
3	N100-220	1497	402	1/3
	N100-219			
4	N100-221	1530	420	1/3
5	N100-313	489	397	1/3
6	N100-411	1497	60	1/3
7	N100-911	1507	429	1/3
8	N100-001	483	196	2/3
9	N100-002	414	482	2/3
10	N100-102	464	420	2/3
11	N100-119	464	420	2/3
12	N100-501	350	120	2/3
13	N100-502	350	120	2/3
14	N100-503A	431	120	2/3
15	N100-901	446	350	2/3





3x c818	9x Ø 6,3x13 mm e2	8x Ø3,5x15 mm p51	1x z1	15x l2	16x Ø15x12 mm #16 r1	16x r42	20x Ø8x30 mm f1
2x 350 mm w207/1	2x 350 mm w207/2	14x Ø7x50 mm e1	6x Ø3,5x12 mm p140	6x Ø6x13 mm e3	4x Ø5x50 mm e32	2x Ø6,3x15 mm d5	12x Ø16 s2
6x Ø3,5x13 mm p1	4x a27	4x b13	20x Ø3,5x16 mm p38	2x k129	1x k38 ⁷	1x k38 ³	



1








2




3



4



5



6

