












Спейс / Space



модуль 3 (h-2200*800) d=420 /
module 3 (h-2200*800) d=420







 (A1) 8*30mm x8	 (C1) 6*43mm x24	 (D) $\varnothing$ 20mm x24
 (D1) 15/15 x24	 (E6) 3,5*16mm x16	 (2E) 4,2*16mm x2
 (G5) M 4*20mm x6	 (K16) $\varnothing$ 50*h27mm x4	 (L24) x8
 (O8) L-2141 mm x1	 (R3) 1.4*25mm 35g	 (S16) 260.54.900 x1
 (U3) x4	 (E15) 4*30mm x8	




№	a*b	x	№→...
1	2142x400x16	x1	2/2
2	2142x400x16	x1	2/2
3	800x400x16	x1	1/2
4	800x400x16	x1	1/2
5	768x400x16	x4	1/2
6	2171x397x4	x2	2/2
		x1	1/2


№	a*b	x	№→...
8/1	2170x397x16	x1	1/1
8/2	2170x397x16	x1	1/1
	 L-1000mm	x1	1/1
	 L-600mm	x1	1/1








 A1 8*30mm x4	 C1 6*43mm x8	 D1 15/16 x4
--	--	---



1



 A1 8*30mm x4	 C1 6*43mm x8	 D1 15/16 x4
---	---	--


2




 (C1) 6*43mm x8	 (D1) 15/16 x16
--	--

3


x4





4




5





6



 (K16) $\varnothing 50 \times h 27 \text{ mm}$ x4	 (O8) L-2141 mm x1
--	--



7



8










9




2E


4,2*16mm



x2




 E6 3,5*16mm x16	 L24 x8
---	--

10




 (G5) M 4*20mm x6	 (I56) L-600 mm x1	 (I56) L-1000 mm x1
--	--	--

11



12

 D $\phi 20\text{mm}$ x20	 U3 x4
--	---



13

