



















DRESSING TABLE

ARBOR DREV




DRESSING TABLE

A0  8x50 x8	B1  3,5x35 mm x8	M01  x6
D2  3,5x16 mm x8	D4  3,5x35 mm x2	P0  x6
J1  x6	J2  M8 x6	T1  x4
N4  L-400 x1	Z  x1	








DRESSING TABLE














Colli 1/1: 1 2 3 4 5 6 7 8 9 10

1







2





A0  8x50 x4	J1  x2	D2  3,5x16 mm x4
N4  L-400 x1	T1  x4	






3






4





5



6



7



8

